



Release Notes

Honeywell Voice for Manhattan Active 3.6.1

June 9 2023

New Features in this Release

Single Sign On

Single Sign On (SSO) support added for Android. User can change the login type from the Overflow menu (local or SSO). DefaultLogin can also be used to configure the login type via settings. See Configuration Settings, below.

Configuration Settings

DefaultLogin

Selects the type of login to use:

- Login: Username, password used for login)
- SSO: Single Sign On used for login The default is Login.

NOTE

Single Sign On is only supported for Android devices.

ShowLoginTypeMenuItem

Allows the user to view the login type (default or SSO, see DefaultLogin above) from the overflow menu. The user may also change the type of login without accessing the settings.

- True: the user can view and change the login type.
- False: the user cannot view or change the login type. The default is False.

Issues Fixed and Included in This Release

- Fixed LookAhead async workflow issue.
- Fixed LookAhead async quantity issue.

- See HVMA 3.4.0 Features for the original description of the feature. For the feature associated with State Type LookupTextField, the key must be all uppercase letters and/or numbers with NO spaces. When the key and value are the same HVMA will speak the value phonetically.
- In the previous new feature for lookahead (see HVMA 3.5.0 Features) there is a scenario where using an action item would cause the prompt to be stored and spoken to the user prior to the next prompt. Some additional checks were added to prevent this issue from occurring.
- Fixed showing error if it occurs after showing lookahead feature.
- Issue resolved where HVMA would make a duplicate request during LookAhead Feature.
- Issue resolved where HVMA would not speak a prompt when speaking "say again" on A700x during LookAhead Feature.

System Requirements

The following devices and software were tested for this release.

Minimum Android Device Specifications

- **Processor:** Qualcomm Snapdragon 410 MSM8916 1.2 GHz quad-core
- **Memory:** 2GB RAM
- **Storage:** 8GB/16GB Flash
- **WLAN:** IEEE 802.11 a/b/g/n radio
- **Bluetooth:** Bluetooth Class 4.0, Bluetooth HFP (Hands-Free Profile) version 1.6
- **Operating System:** Android O (8)

The above are the minimum recommended device specifications. If the device does not meet or exceed these specifications, the following symptoms may occur:

- Poor audio quality
- Slow application screen responsiveness
- Delayed input entry

Hardware

The following devices were tested for this release.

Devices

- Honeywell CT40
- Honeywell CT40 XP

- Honeywell CT45
- Honeywell CT60
- Honeywell CT60 XP
- Honeywell CK65
- Honeywell CW45
- Honeywell A700x
- Zebra WT6300
- Zebra TC5x
- Zebra TC7x

Headsets

- Honeywell SRX-SL Light Industrial Use Headset
- Honeywell SRX2 Wireless Headset (with Hands-Free Profile support)
- Honeywell SRX3 Wireless Headset

Scanners

- Honeywell CT40 On-board Scanner
- Honeywell CT45 On-board Scanner
- Honeywell CT60 On-board Scanner
- Honeywell A730x On-board Scanner
- Honeywell 8670 Ring Scanner

Android Device Operating System Support

- Android O (8.1.0)
 - Honeywell Dolphin CT40
 - Honeywell Dolphin CT60
 - Honeywell Dolphin CK65
 - Honeywell ScanPal EDA51
 - Honeywell ScanPal EDA71
- Android P (9)
 - Honeywell Dolphin CT40
 - Honeywell Dolphin CT60

- Honeywell CK65
- Android 10
 - Honeywell CT40
 - Honeywell CT40 XP
 - Honeywell CT60
 - Honeywell CT60 XP
 - Honeywell CK65
- Android 11
 - Honeywell CT40
 - Honeywell CT40 XP
 - Honeywell CT45
 - Honeywell CT60
 - Honeywell CT60 XP
 - Honeywell CK65
- Android 12
 - Honeywell CW45

Honeywell A700x Software Support

- VoiceCatalyst 4.5 or greater

General Considerations and Limitations

Previously Reported Limitations

Issue Description	Issue ID
<p>DisableVocabWord is Case Sensitive</p> <p>The A700x device setting DisableVocabWord is case sensitive and the format is DisableVocabWord_vocab_word (where DisableVocabWord is camelCase and the vocab-word is lower case).</p>	<p>VOSMB-5363</p>

Issue Description	Issue ID
<p>Do Not Press + and – Buttons on SRX3 Headset to Unpair</p> <p>When unpairing your SRX3 headset from an Android device, do not press the + and – buttons simultaneously. This procedure causes known issues with TTS and speech recognition.</p> <p>Proper Procedure: To unpair your SRX3 headset from an Android device, go to your device Bluetooth settings, display the Paired devices screen, select the headset, and tap FORGET to unpair the headset and the Android device.</p>	VOSMB-1448
<p>"GatewayTimeout" error message from Microservices</p> <p>If the mobile application has trouble reaching the Microservices host ("GatewayTimeout") while attempting to retrieve templates it may force the user to retrain all words for that workflow.</p> <p>Workaround: If you experience this behavior close and restart the app and log in again</p>	VOSMB-971
<p>Errors while Transmitting Files to VoiceConsole</p> <p>A number of errors may appear in the device logs when transmitting logs to VoiceConsole. In spite of these errors, all log files are eventually transmitted successfully.</p>	VOSMB-570
<p>Do Not Press Next Button Quickly</p> <p>If you have untrained words and get to the template training instructions screen, if you tap the Next button in rapid succession, it can cause the application to shut down unexpectedly.</p>	VOSMB-230
<p>Audio to the Bluetooth Headset Can Fail</p> <p>In some situations, the audio no longer comes through a Bluetooth headset even though it is still paired to the device.</p> <p>Workaround: Unpair and re-pair the headset.</p>	VOSMB-28